


Installation Guide

Included Installation Instructions

Dome cover

Model No. WV-QDC511C



- Before attempting to connect or install this product, please read these instructions carefully and save this manual for future use.
- The external appearance and other parts shown in this manual may differ from the actual product within the scope that will not interfere with normal use due to improvement of the product.
- Read also the installation guide of the camera to be used.

i-PRO Co., Ltd. assumes no responsibility for injuries or property damage resulting from failures arising out of improper installation or operation inconsistent with this documentation.

"<Control No.: C***>" used in these documents should be used to search for information on our technical information website (https://i-pro.com/products_and_solutions/en/surveillance/learning-and-support/knowledge-base/technical-information) and will guide you to the right information.



i-PRO Co., Ltd.

<https://www.i-pro.com/>

Caution:

- Before attempting to connect or operate this product, please read these instructions carefully.

Precautions**■ Do not use this product except with suitable cameras.**

Failure to observe this may cause a drop resulting in injury or accidents.

■ Refer installation work or dome cover replacement to the dealer.

Installation work requires technique and experience.

Failure to observe this may cause fire, electric shock, injury, or damage to the product.

Be sure to consult the dealer.

■ The screws and bolts must be tightened to the specified torque.

Failure to observe this may cause a drop resulting in injury or accidents.

When using this product, also read the “Precautions” described in the operating instructions for the camera to be attached.

Preface

This product is the clear type dome cover.



The latest information about the supported cameras
<Control No.: C0501>

Specifications

Ambient operating temperature:	−40 °C to +60 °C {−40 °F to +140 °F}
Dimensions:	ø81 mm × 22 mm (H) {ø3-3/16 inches × 7/8 inches (H)} Dome radius: 35 mm {1-3/8 inches}
Mass:	Approx. 22 g {0.05 lbs}
Finish:	PC resin Clear (with Anti Reflective coating)

Precautions for installation

■ Screw tightening

Do not use an impact driver. Use of an impact driver may damage the screws or cause tightening excessively.


Standard accessories




Waterproof rubber ×1

Installation


Step 1 Preparations



Step 2




- Be sure to replace the waterproof rubber with a new one from the accessories.




- When installing a new dome cover, first remove the protective film and attach the dome cover. After installation is complete, reapply the protective film.

Position of the wire fixing screw



Recommended tightening torque:
1.4 N·m {1.03 lbf·ft}




Step 3

Wire fixing screw
(M3 x 6 mm {1/4 inches})


Top cover support wire



Recommended tightening torque:
0.8 N·m {0.59 lbf·ft}





- When attaching the TOP Cover to the camera, make sure that the Installed auxiliary wire is not caught or pinched.



Recommended tightening torque:
1.4 N·m {1.03 lbf·ft}



Bit (T20 :
camera
accessory)




取扱説明書 **設置ガイド**

工事説明付き

ドームカバー

品番 **WV-QDC511C**



このたびは、弊社製品をお買い上げいただき、まことにありがとうございます。

- 取扱説明書をよくお読みのうえ、正しく安全にお使いください。
- **ご使用前に「安全上のご注意」を必ずお読みください。**
- この取扱説明書は大切に保存してください。
- 製品の改良などにより、ご使用上影響のない範囲で、記載されている外観などが実際の製品と異なる場合があります。
- ご使用のカメラの取扱説明書とあわせてお読みください。

取扱説明書に記載されていない方法や、指定の部品を使用しない方法で施工されたことにより事故や損害が生じたときには、当社では責任を負えません。また、その施工が原因で故障が生じた場合は、製品保証の対象外となります。

i-PRO製品の「お問い合わせ」については、以下の弊社サポートウェブサイトをご参照してください。

https://i-pro.com/products_and_solutions/ja/surveillance/contact-us

※「日本エリア」でお使いの場合に限ります。日本以外でお使いの場合のサービスはいたしかねます。

取扱説明書に記載されている「<管理番号：Cxxxx>」は、以下の弊社技術情報ウェブサイト内で該当する情報を検索する際に使用する番号です。

https://i-pro.com/products_and_solutions/ja/surveillance/learning-and-support/knowledge-base/technical-information



i-PRO株式会社

<https://www.i-pro.com/>

注意：

- 取扱説明書をよくお読みのうえ、正しく安全にお使いください。

安全上のご注意 **必ずお守りください**

人への危害、財産の損害を防止するため、必ずお守りいただくことを説明しています。

■ 誤った使い方をしたときに生じる危害や損害の程度を区分して、説明しています。



警告 「死亡や重傷を負うおそれがある内容」です。

■ お守りいただく内容を次の図記号で説明しています。（次は図記号の例です）



してはいけない内容です。



実行しなければならない内容です。



警告



■ 専用のカメラ以外には取り付けない
（落下によるけがや事故の原因となります。）



■ 工事またはドームカバー交換は販売店に依頼する
（工事には技術と経験が必要です。火災、感電、けが、器物損壊の原因となります。）
⇒ 必ず販売店に依頼してください。

■ ねじやボルトは指定されたトルクで締め付ける
（落下によるけがや事故の原因となります。）

本製品をご使用の際は、取り付けるカメラの取扱説明書に記載された「安全上のご注意」とあわせてお読みください。

商品概要

本製品はクリアタイプのドームカバーです。



取り付け可能なカメラの最新情報

<管理番号：C0501>

仕様

使用温度範囲	−40℃～+60℃
寸法	φ81 mm × 22 mm (H) ドーム半径：35 mm
質量	約22 g
仕上げ	PC樹脂 クリア（反射防止コーティング）

設置上のお願い

■ 取付ねじの締め付けについて

インパクトドライバーは使用しないでください。ねじが破損したり締め付けすぎたりします。


付属品をご確認ください




防水ラバー ×1

設置する



Step 1 前準備



Step 2




- 付属品の新しい防水ラバーに必ず交換してください。




- 新しいドームカバーを取り付ける際には、一旦保護フィルムを外してドームカバーを取り付け、取付完了後に再度、保護フィルムを貼り付けてください。

ワイヤー固定ねじ
取付位置



推奨締付トルク:
1.4 N·m {14.28 kgf·cm}




Step 3

ワイヤー固定ねじ
(M3 x 6 mm)




推奨締付トルク:
0.8 N·m {8.16 kgf·cm}

上カバー保持ワイヤー



- トップカバーをカメラに取り付ける際には、設置補助ワイヤーが噛み込んでいないことを確認してください。



推奨締付トルク:
1.4 N·m {14.28 kgf·cm}



ビット (T20 :
カメラ付属品)

